



Inspection No.: 221593

## REPORT OF THIRD PARTY INSPECTION

**Order No.:** 748295765

**Commodity description:** Stainless steel Tube and Fittings

**Quantity:** --

**Manufacturer:** FITOK INCORPORATED

**Contact Person:** Mr. Cheng Pengfei

**Inspection Place:** 1-4F, Block C, Zone E, Yingtai Industrial Park,  
Dalang Street, Bao' an District, Shenzhen,  
Guangdong, 518109, China

**Inspection Date:** 2014-12-15~16

**Inspector:** Mr. Xu Zhujun

**Product ID Number:** Samples as report

TÜV SÜD Industrie  
Service GmbH  
Shanghai Office

No. 88 Heng Tong Road,  
Shanghai 200070, P.R.China  
Telefon +86 21 6141 0123  
Telefax +86 21 6141 8600  
Internet: www.tuv-sud.cn  
E-mail: zhujun.xu@tuv-sud.cn

Westendstraße 199  
D-80686 München  
Telefon (0 89) 57 91-11 21  
Telefax (0 89) 57 91-22 62

Das Dokument besteht aus:  
4 Seiten

Die auszugsweise  
Wiedergabe des  
Dokumentes und die  
Verwendung zu  
Werbezwecken bedürfen  
der schriftlichen  
Genehmigung der  
TÜV SÜD Industrie  
Service GmbH

